

# State of Utah

### Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

## Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	David Shaver Manager					
OGM	Karl Houskeeper Environmental Scientist III					

# **Inspection Report**

Permit Number:	C0070033 PARTIAL			
Inspection Type:				
Inspection Date:	Tuesday, July 29, 2008			
Start Date/Time:	7/29/2008 7:30:00 AM			
End Date/Time:	7/29/2008 9:30:00 AM			
Last Inspection:	Monday, June 30, 2008			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 72 Deg. F. InspectionID Report Number: 1714

7/30/2008

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

### **Current Acreages**

100.00	Total Permitted		
63.70	<b>Total Disturbed</b>		
	Phase I		
	Phase II		
	Phase III		

### **Mineral Ownership**

#### **Types of Operations** ■ Underground ✓ Federal State Surface **✓** Loadout ☐ County ✓ Processing Fee ☐ Other ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to quarterly electronic water monitoring submittals.

There are no pending compliance actions

Inspector's Signature:

Date

Tuesday, July 29, 2008

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 29, 2008

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>✓</b>		<b>V</b>	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>V</b>			
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	<b>✓</b>	<b>~</b>		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		<b>✓</b>	
8.	Noncoal Waste	<b>✓</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 29, 2008

Page 3 of 3

### 2. Signs and Markers

The mine ID signs are at the point of public access to the permit area and contain the required information.

# 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ponds A, B, C, D, and E were dry at the time of the inspection.

# 7. Coal Mine Waste, Refuse Piles, Impoundments

The pile appeared stable. No visible hazards were noted.